



# anchor industries




## Center Support Bearing Product Alert Part #'s 6061 & 6062

It has come to our attention that the packaging of Anchor part numbers 6061 and 6062 is causing confusion since the parts are so similar. While the parts may look identical, the inside bearing on 6061 is 1.257" and the inside bearing diameter on 6062 is 1.181".

**6061 inside bearing diameter = 1.257"**

**6062 inside bearing diameter = 1.181"**

**Please physically check your inventory to confirm that the parts are packaged correctly per the inside diameter.**



January 28, 2010

